

Speed Test Results

15-Yard Bill Drill

	Average Time	Improvement Over Stock Gun
Stock	2.72 seconds	0% (baseline)
Ed Brown Four Star	2.65 seconds	2.6%
Storm Lake Tri-Port	2.32 seconds	14.7%
Wilson Dot Tracker	2.34 seconds	14.0%

Speed Plates, 15 Yards

	Average Time	Improvement Over Stock Gun
Stock	4.64 seconds	0% (baseline)
Ed Brown Four Star	4.14 seconds	10.8%
Storm Lake Tri-Port	3.99 seconds	14.0%
Wilson Dot Tracker	3.49 seconds	24.8%



Left: In the Bill Drill, the Storm Lake Machine Tri-Port compensator had some tendency to bounce as the slide slammed home.