

## SPRINGFIELD STANDARD WIDE BODY PB9707

The forward portion of the chrome-moly barrel is Parkerized. We think this contributed to malfunctions

Sights are a fixed three-dot system, but the front dot is obscured with what appears to be Parkerize bleeding. The sights are tall and very readable

The gun shot a little higher than point of aim

The beavertail is not of the fully smoothed competition variety and takes some care during fast draws to avoid biting the hand

Grips are thin plastic to compensate for the wider grip, but can be thinned further to fit the individual shooter

