

This model's aluminum alloy receiver won't rust, but it also won't be as durable as steel. The walnut stock was nice looking, but the forend had an excessive amount of side-to-side play.