

The Model 70 BDL SS DM-B's jewled bolt operated smoothly. But, when the magazine was full, a very hard push was needed to strip the first round from the magazine and into the chamber.